

Figure 2: Soils Map for WH22/Kilns Demolition Project



Tables — Drainage Class — Summary By Map Unit				
Summary by Map Unit — Columbia County, Oregon (OR009)				
Summary by Map Unit — Cowlitz County, Washington (WA015)				
Summary by Map Unit — Columbia County, Oregon (OR009)				
Map unit symbol	Map unit name	Rating	Acres in AOI	Percent of AOI
61	Udipsamments, nearly level, protected	Well drained	0.0	0.0%
W	Water		50.4	3.6%
Subtotals for Soil Survey Area			50.4	3.6%
Summary by Map Unit — Cowlitz County, Washington (WA015)				
Map unit symbol	Map unit name	Rating	Acres in AOI	Percent of AOI
17	Caples silty clay loam, 0 to 3 percent slopes	Somewhat poorly drained	286.0	20.4%
127	Maytown silt loam, 0 to 3 percent slopes	Moderately well drained	5.4	0.4%
141	Newberg fine sandy loam, 0 to 3 percent slopes	Well drained	59.8	4.3%
160	Pilchuck loamy fine sand, 0 to 8 percent slopes	Somewhat excessively drained	811.7	57.8%
263	Water		191.7	13.6%
Subtotals for Soil Survey Area			1,354.6	96.4%
Totals for Area of Interest			1,405.0	100.0%